## Department of Public Works Solid Waste Management Administration

## TABLE OF CONTENTS

EXECUTIVE SUMMARY
INTRODUCTION
Background
Scope and Methodology
Compliance and Follow-up
EMPLOYEE SURVEY. 5
FINDINGS AND RECOMMENDATIONS
SOLID WASTE DISPOSAL DIVISION. 6
Rodents Not Controlled At Transfer Stations
Walls, Floors at Transfer Stations Not Cleaned as Required 8
Leaking Contractor Vehicles Violate District Regulations
Waste Hauled by Contractor Not Weighed At Transfer Stations
Employees Not Wearing Protective Equipment, Clothing
Employees Report Poor Ventilation, Breathing Problems
Unrepaired Sprinkler System Linked to Respiratory Problems
Additional Fixed Ladder Needed on Conveyor Platform
Conveyor Belts, Overhead Crane Need Immediate Replacement 14
Inefficient Communication Creates Potential for Accidents
Obsolete Incinerator Flue is Potential Safety Hazard
Security Cameras Needed to Combat Illegal Dumping
Required Identification Signs Not Posted At BRTS
Division Has No Written Policies, Procedures
BRTS, FTTS Building Designs Need Updating
SOLID WASTE COLLECTION DIVISION 23
Division Not Complying With Law on Eye and Face Protection
Division Not Complying With Protective Footwear Law
Division Not Complying With Agreement on Protective Gloves
Employees Not Issued Required Uniforms
Hazard Cited By OSH at Brentwood Still Uncorrected
Facilities Not Treated Sufficiently to Eradicate Pests, Rodents

Poor Air Quality Noted at South Capitol Street Facilities	30
Employees Say Crane Carrier Trucks Not Safe or Comfortable	30
Radio Equipment Not Effective	32
Number of Vehicles for Daily Collections Insufficient	33
SWEEP Response to Collection Problems Inadequate	34
Maintenance on Collection Vehicles Not Current	35
Collection Trucks Not Properly Cleaned Prior to Storage	. 37
New Collection Truck Employees Not Adequately Trained	. 38
Dead Animal Collection Unit Lacks Appropriate Equipment	.39
Bulk Collection Unit Without Adequate Office Space	40
Field Locations Do Not Have Adequate Office Equipment	. 40
Brentwood Road Ladies Room Used by Male Employees	42
Regulations on Performance Appraisals Not Being Followed	.42
Employees Not Given Copies of Performance Evaluations	. 43
No Written Procedures for Future Foreman Training Program	.44
Some Supervisors Reportedly Disrespectful to Employees	44
Employees Want More Frequent Meetings With Management	45
EEO/Sexual Harassment Policies Not Promulgated	45
Division Lacks Written Policies and Procedures	46
Personal Cell Phone Use on Duty Poses Hazard	47
Education of Residents on Division Services Deficient	.47
FREET AND ALLEY CLEANING DIVISION	
Refueling of Tennant Vacuums May Endanger Employees, Public	
Provision, Use of Personal Protective Equipment Inadequate	
Lack of Radio Equipment a Safety Hazard to Vehicle Operators	
Number of Mechanical Sweepers Insufficient to Clean City	
Wards 3, 8 Not Receiving Scheduled Street Sweeping	
Motorized Vehicle Fleet Old, Overused, Not Maintained	
Fleet Services Garage Lacks Parts to Repair SAC Vehicles	
SAC Supervisors Months Behind in Responding to Service Complaints	
Sweeper Operators, Dump Truck Drivers Need Radios for Coordination	
Sweeper Operators Not Given Standardized Training	
Division Managers, Supervisors Need Service Delivery Training	
Employees Working in Higher-Graded Positions Without Additional Pay.	
Lack of Updated Position Descriptions	
Employees Say Outstanding Performance Not Recognized	
Seniority Clauses Seen As Creating Unfair Promotion Process	
Some Supervisors Not Keeping Records on Employee Performance	68

SOLID WASTE EDUCATION and ENFORCEMENT PROGRAM	
(SWEEP)	<del>70</del>
SWEEP Too Understaffed to Carry Out All Assigned Tasks	70
Some Inspectors Concerned About Security While in the Field	7
Managers, Employees Cite Health Hazards At Headquarters Building	71
Inspectors Not Receiving Hazardous Materials Pay	72
Inspectors Not Trained on Proper Ticket Writing	73
Information on Sanitation Violations Not Used to Improve Operations	
73	
A Number of Employees Say Unit Morale Is Low	
74	
SWEEP Jr. Program Not Sufficiently Funded	
75	